Atty. Ref.: 9694-000003/NP

1/21

BEST AVAILABLE COPY

Fig. 1




Fig. 2








Fig. 3








4/21

















Fig. ZOA



12/21

Fig, 20B






Fig. 20C



14/21


Fig. 20D




10/502457

15/21

Fig. 20E



16/21



To/From SDL
Control Signals Storage Element interface




Fig. 23






Fig. 24



20/21




Title: DATA STORAGE SYSTEM
Inventors: Kirk Donald WILSON, et al.

Atty. Ref.: 9694-000003/NP

21/21

Fig. 26



10.1502 457

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
OTHER.

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.